

## SUMMARY

21 Cotman Cres, Toronto, ON May 6, 2011

Report No. 25771

www.carsondunlop.com

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

MORE INFO

### INTRODUCTION

This Summary lists some of the significant report items that may need attention in the short term. This must not be considered as the complete report. Please read the entire report and the appropriate text included in the provided hyperlinks.

### COOLING

#### **AIR CONDITIONING SYSTEM - GENERAL \ 1.0 & 18.0**

**Condition:** • [Old](#)

**Task:** Replace

**Time:** Unpredictable/ As Required

**Cost:** \$3,000 - and up

END OF SUMMARY

#### NOTE: BALLPARK COSTS AND TIME FRAMES

Any ballpark costs and time estimates provided are a courtesy and should not be relied on for budgeting or decision-making. Quotations from specialists should be obtained. The word 'Minor' describes any cost up to roughly \$500.